



Repair Parts for 800 Air Grinder

FOREDOM #800
GRINDER

Foredom Part No.	Description	Price
HPFGM-4320A	Exhaust Hose Assembly	\$20.00
2597	Bulk Exhaust Hose	6.25
Not Available	Upper End Plate Assembly	Not Available
2230	Hex Lock Nut	1.30
2210	Cylinder	44.50
2495	Rotor Blade (5 per motor)	3.50/each -
2698A	Muffler Hose Assembly	35.00
2207	Distributor	13.60
2211	Alignment Pin	2.00
2699	Housing	55.00
4331	Replacement Rotor Assembly	105.00
3115A	Motor Assembly	187.00
4317A	Head Assembly	165.00

FOREDOM®

The Foredom Electric Company

16 Stony Hill Road, Bethel, CT 06801, USA • Tel.: 203-792-8622 • Fax: 203-796-7861 •

Email: customerservice@blackstoneind.com • www.foredom.net

Revised 3/2012 n

Printed in USA